

# Avaya

## Exam Questions 75940X

Avaya Converged Platform Integration Exam



#### NEW QUESTION 1

Why does enabling VMware Enhanced vMotion Compatibility (EVC) prevent vMotion migrations from failing?

- A. Because of incompatible DRS rules across the cluster
- B. Because of incompatible HA rules across the cluster
- C. Because of insufficient memory across the cluster
- D. Because of incompatible CPUs across the cluster

**Answer: D**

#### NEW QUESTION 2

How can the administrator check the status of all services being monitored by Avaya Orchestrator?

- A. It is not possible
- B. Services are displayed on a per-Host basis only.
- C. By navigating to Quick View-All Service Problems.
- D. By navigating to Details-Service Status.
- E. By navigating to ACP 4200 Configuration Wizard-Service.

**Answer: B**

#### NEW QUESTION 3

Refer to the exhibit.

The CPU performance of Communication Manager (CM) shows a significant difference depending on the call rates. Which statement about making configuration changes is true?

- A. Increasing the number of Virtual CPUs allocated to CM might help to reduce this difference.
- B. Ensuring that a secondary CM is available to allow for load-balancing might help to reduce this difference.
- C. Migrating the CM Virtual Machine to another ESXi host that is less busy might help to reduce this difference.
- D. Reducing this difference is not necessary because this is expected behavior.

**Answer: B**

#### NEW QUESTION 4

An ACP 4200 engineering team is considering deploying an Extension Rack. What is the purpose of the Extension Rack?

- A. When the Main rack is not functioning properly the Extension Rack will take over for the main.
- B. When all hardware components cannot fit into the Main ACP Rack, Extension Racks are used for additional physical appliances and servers.
- C. When full redundancy is needed, Extension Racks are used for additional physical appliances and servers.
- D. When the number of telephone extensions on the Avaya Aura® applications exceed the recommended limit, Extension Racks are used to host additional media resources to support a higher limit.

**Answer: C**

#### NEW QUESTION 5

An Avaya Orchestrator administrator is asked to check the CPU usage for the last 24 hours of one of the ESXi Hosts, as it has been performing erratically. How can the administrator go about doing this?

- A. By clicking on the Compute Group's Service State line.
- B. By navigating to Quick View – All Host Problems.
- C. By going to the Performance Graphs of the CPU Usage Service for the host.
- D. By selecting the VM Group's Service State line.

**Answer: A**

#### NEW QUESTION 6

After implementing a new ACP 4200 solution, warnings about high temperatures on one of the host servers are reported by the Avaya Orchestrator. To verify the temperature, fan speeds, and general hardware health of the HP Servers in the ACP 4200, which third party management tool can be used?

- A. Nimble storage web interface
- B. ESXi server client
- C. HP iLO web interface
- D. vSphere Web Client

**Answer: C**

#### NEW QUESTION 7

Refer to the exhibit.

Which Avaya Session Border Controller for Enterprise (ASBCE) configuration option is shown?

- A. High Availability
- B. Hybrid
- C. Geographic Redundancy
- D. Two-wire

**Answer: A**

**NEW QUESTION 8**

A new ESXi host has been added to the ACP 4200. However, unlike existing ESXi hosts within the ACP 4200, the new host cannot be monitored or detected by Avaya Orchestrator.

What is causing this problem?

- A. The new host has not been correctly configured to support vMotion.
- B. The new host has not been added to Avaya Orchestrator.
- C. The new host has not been licensed yet.
- D. The new host has not been configured for Auto Detection.

**Answer: B**

**NEW QUESTION 9**

Refer to the exhibit.

An administrator navigates to the Avaya Orchestrator page shown in the exhibit. The 4850GTS switches and the PIPS Pro1 PDUs are displaying an Orange status icon.

What does this indicate?

- A. These devices have not been configured with correct credentials.
- B. These devices have power supply issues.
- C. These devices have services with status of warning.
- D. These devices have reachability issues.

**Answer: C**

**NEW QUESTION 10**

Refer to the exhibit.

What does the IP address 10.1.1.1 represent?

- A. The IP address of the EMC storage
- B. The SMLT IP address of the two VSP 7200 switches
- C. The Virtual IST IP address of the two VSP 7200 switches
- D. The VRRP IP address of the two VSP 7200 switches

**Answer:** D

**NEW QUESTION 10**

When planning to add additional VMs to an ACP 4200, to determine if an additional host server would be required, which tool can be used?

- A. The Server resource calculator from the VMware vCenter client.
- B. The Server Calc worksheet in the Lifecycle workbook.
- C. The Server resource calculator tool in the Lifecycle workbook.
- D. The Server calculator tool from Avaya Orchestrator.

**Answer:** D

**NEW QUESTION 14**

What is the role of Avaya Aura® System Manager in an ACP 4200 4.0 system?

- A. It provides a Single-Sign On functionality to Avaya Orchestrator.
- B. It manages the license for Avaya Orchestrator.
- C. It provides the application launch point for Avaya Orchestrator.
- D. It is a component of the Avaya Aura® deployment.

**Answer:** B

**NEW QUESTION 17**

Refer to the exhibit.

An Administrator notices that a Service Status Warning is being received by Avaya Orchestrator indicating that port 27 on VSP 4850-1 is down. Based on the contents of the Customer and Network Lifecycle Workbook in the exhibit, which equipment is connected to this port?

- A. VSP4K1, port 27
- B. Server/ACR-2, Interface NO
- C. Server/ACR-1, Interface NO
- D. VSP4K1, Port 26

**Answer:** A

**NEW QUESTION 19**

Which Extreme Networks switch model is used in a new ACP 4200 release 4.0?

- A. VSP 4850
- B. VSP 7254
- C. VSP 8400
- D. VSP 7024

**Answer:** B

**NEW QUESTION 21**

The customer's networking team is considering connectivity options to the ACP 4200.

For which customers would an ACP 4200 Layer 2-only networking topology be deployed, and why?

- A. Customers who have a Layer 2 Data Center
- B. The ACP will provide Layer 3 routing for the customer.
- C. Customers who wish to retain existing VLANs, subnets, and IP subnet
- D. The ACP will extend VLANs out to the Data Center routers which will provide Layer 3 routing.
- E. Customers who do not use Dynamic routing protocol
- F. The ACP will use static routes for connectivity to the Data Center.
- G. Customers who wish to upgrade their Data Center to Fabric Connected
- H. The ACP will use Fabric Extend to integrate with the customer's Data Center switches.

**Answer:** D

**NEW QUESTION 23**

When preparing a site for an ACP 4200 installation, which task is optional?

- A. Identify potential obstacles, such as signs and fire extinguishers in the path from the delivery location to the permanent site.
- B. Plan the path from the delivery location to the permanent site.
- C. Ensure that a minimum of four people are available to move the ACP 4200 due to its size and weight.
- D. Ensure there is a room to maneuver the ACP 4200 around any tight corners in hallways.

**Answer:** A

**NEW QUESTION 28**

.....

## **Thank You for Trying Our Product**

### **We offer two products:**

1st - We have Practice Tests Software with Actual Exam Questions

2nd - Questions and Answers in PDF Format

### **75940X Practice Exam Features:**

- \* 75940X Questions and Answers Updated Frequently
- \* 75940X Practice Questions Verified by Expert Senior Certified Staff
- \* 75940X Most Realistic Questions that Guarantee you a Pass on Your FirstTry
- \* 75940X Practice Test Questions in Multiple Choice Formats and Updatesfor 1 Year

**100% Actual & Verified — Instant Download, Please Click**  
**[Order The 75940X Practice Test Here](#)**